Customer: State Geological Institute of Dionyz Stur

Mlynská dolina 1 817 04 Bratislava

Telephone no.: +421/259375232
Fax: +421/259375232
Tax ident. no.: 2020719646
Ident. no. VAT: SK 2020719646
Ident. no. of organisation: 31753604
Bank: Štátna pokladnica

Account no./IBAN:SK37 8180 0000 0070 0039 0960

Bank code: 8180

Delivery and payment conditions: 30 days since delivery of invoice.

Delivery date: within 30 days since delivery of appropriate

order

Place of delivery:

By e-mail to the address: ivan.dananaj@geology.sk

Order

No : 10/110/2019 In Bratislava, 4.3.2019

SUPPLIER:

GLÖTZL Gesellschaft für Baumesstechnik mbH,

Forlenweg 11,

D – 76287 Rheinstetten

Deutschland

IČO: DE 143241608

The invoices send in two copies to the address:

Štátny geologický ústav Dionýza Štúra

Mlynská dolina 1 817 04 Bratislava Slovak Republic

	•		<u> </u>
Item	Quantity	Part	Subject
			In sence of your quotation dated February 22, 2019, we order in your company the calibration and service of inclinometer probes in the range:
			 Check and Maintenance of your inclinometer probes S / N 11 002265 and S/N 14 002370 including check of the probes, recalibration of the probes including certificates, test measurement with evaluation and documentation;
			- Exchange of defective wheels of the probe no. 11 002265 Lump Sum for material including working time;
			- Exchange of the 2 defective wheels of a blind probe lump sum for working time including material;
			- 50 m new cable, marked (including assembling)
			- transport of probes after calibration and service to delivery point

Responsible person: Ing. Ľ. Sokolíková +421 905 225 328

Eng. Branislav Žec, CSc. General director

NOTE: Please, write on the invoice the order number